









Date: Thursday, 31/07/2008 9:27:09 AM
 User: Melanie Fauteux

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: D344613
Job Number	: 40839		
Estimate Number	: 10804		
P.O. Number	:	Part Number	: D344613
This Issue	: 31/07/2008	S.O. No.	:
Prsht Rev.	: NC	Drawing Number	: DISASSEMBLE
First Issue	: 31/07/2008	Project Number	:
Previous Run	: 00015	Drawing Revision	:
Written By	:	Material	:
Checked & Approved By	: <u>mf 08-07-31</u>	Due Date	: 31/07/2008
Comment	:	Qty:	3
		Um:	Each

Seq. #:	Machine Or Operation:	Description :
1.0	PACKAGING 1	PACKAGING RESOURCE #1
		
Comment: PACKAGING RESOURCE #1 PULL FROM STOCK: D3446-043 QTY X 3 REMOVE D3446 ¹³ (MALE BUCKLE)		
2.0	D3446043	Harness Assembly
		
Comment: Qty.: 1.0000 Each(s)/Unit Total : 3.0000 Each(s) Harness Assembly B# <u>40426</u> <u>8/7/30</u> <u>34</u> <u>SD</u>		
3.0	PACKAGING 1	PACKAGING RESOURCE #1
		
Comment: PACKAGING RESOURCE #1 REPACKAGE, IDENTIFY AND STOCK D344613 WITH NEW BATCH # LOCATION: SEND REMAINING ITEMS TO QC <u>8/7/31</u> <u>(3)</u>		
4.0	QC5	INSPECT WORK TO CURRENT STEP
		
Comment: INSPECT WORK TO CURRENT STEP <u>8/7/31</u> <u>(3)</u>		

Date: Thursday, 31/07/2008 9:27:09 AM
User: Melanie Fauteux

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D344613

Job Number: 40839

Part Number: D344613

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

QC21

FINAL INSPECTION/W/O RELEASE



08/07/31

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



mf 08-07-31